



[FAQs](#) > [X-TERRA](#) > [X-TERRA VOYAGER](#) > [X-TERRA VOYAGER - Quick Help](#)

X-TERRA VOYAGER - Quick Help

Sarah Schernthanner - 2026-02-27 - [X-TERRA VOYAGER](#)

Quick Help

1. Turn On

Press Power.
Wait 5 seconds for calibration.

2. Start Detecting

Sweep coil side-to-side, close & parallel to the ground.
Coil only detects while moving.

3. Identify Targets

Beep + Target ID (0-99) on screen.
Depth Gauge shows approximate depth.

4. Pinpoint

Hold Pinpoint to locate exact target position.
Sweep slowly for the loudest signal.

5. Adjust Sensitivity

Press Sensitivity to enable → adjust with + / -.
Choose the highest stable level (5 levels).

6. Search Modes

Press Search Mode to cycle:

All Metal (detects everything)
Custom (enable/disable groups)
Jewelry (ignores iron)
Learn (learns one specific target)

7. Batteries

Uses 2× 9V, replace both at the same time.